

09/889269


07/12/2001 22:38 03326

FUKUMORI P.O.

21/48


1/4

FIG. 1



2/4


FIG. 2




3/4

FIG. 3

(10000 Times)





Ra = 3.0 μm




Ra = 2.0 μm




Ra = 1.5 μm



Ra = 1.0 μm




Before corrosion test



Ra = 0.5 μm

After corrosion test



BEST AVAILABLE COPY

BEST AVAILABLE COPY

07/12/2001 22:38 033261

FUKUMORI P.O.

09/889269


4/4

FIG. 4



BEST AVAILABLE COPY

(30000 Times)

Before oxidation processing



Before corrosion test



Before corrosion test

Cleaning with  
ultra pure water  
after corrosion test

2050320 69268360